


HELICOPTER TECHNOLOGY COMPANY – REPAIR STATION #HQPR671X**Introduction Section****Change Letter: K****Change Date: 04/19/2017****VI. Capabilities List**

Part Number	Description	Make/Model	Data Source
500P2100-BSC (STC #SR09172RC)	Blade Assembly, Main Rotor	MDHI 369D, E (H3WE)	HTCQ-004
500P2100-BSC-1 (STC #SR09172RC)	Blade Assembly, Main Rotor	MDHI 369D, E (H3WE)	HTCQ-004
500P2100-101 (STC #SR09074RC)	Blade Assembly, Main Rotor	MDHI 369D, E (H3WE)	HTCQ-004
500P2100-103 (STC #SR09074RC)	Blade Assembly, Main Rotor	MDHI 369D, E (H3WE)	HTCQ-004
500P2100-105 (STC #SR09074RC)	Blade Assembly, Main Rotor	MDHI 369D, E (H3WE)	HTCQ-004
500P2100-301 (STC #SR09184RC)	Blade Assembly, Main Rotor	MDHI 369A, H, HE, HM, HS (H3WE)	HTCQ-004
500P2100-303 (STC #SR09184RC)	Blade Assembly, Main Rotor	MDHI 369A, H, HE, HM, HS (H3WE)	HTCQ-004
500P2100-305 (STC #SR09184RC)	Blade Assembly, Main Rotor	MDHI 369A, H, HE, HM, HS (H3WE)	HTCQ-004
500P2300-501 (STC #SR01050LA)	Blade Assembly, Main Rotor	MDHI 369FF, 500N, 600N (H3WE)	HTCQ-004

Approved: 

Vice President, Quality Assurance


12902 South Broadway • Los Angeles, California 90061

Sheet xvii of xxvii – HTC Proprietary Data Not to be Distributed

HELICOPTER TECHNOLOGY COMPANY – REPAIR STATION #HQPR671X**Introduction Section**Change Letter: **K**Change Date: **04/19/2017****VI. Capabilities List – Cont.**

<u>Part Number</u>	<u>Description</u>	<u>Make/Model</u>	<u>Data Source</u>
500P2300-503 (STC #SR01050LA)	Blade Assembly, Main Rotor	MDHI 369FF, 500N, 600N (H3WE)	HTCQ-004
500P2300-505 (STC #SR01050LA)	Blade Assembly, Main Rotor	MDHI 369FF, 500N, 600N (H3WE)	HTCQ-004
500P3100-101 (STC #SR09213RC)	Blade Assembly, Tail Rotor	MDHI 369D, E (H3WE)	HTCQ-012
500P3100-101I (STC #SR09213RC)	Blade Assembly, Tail Rotor	MDHI 369D, E (H3WE)	HTCQ-012
500P3100-101IT (STC #SR09213RC)	Blade Assembly, Tail Rotor	MDHI 369D, E (H3WE)	HTCQ-012
500P3100-101M (STC #SR09213RC)	Blade Assembly, Tail Rotor	MDHI 369D, E (H3WE)	HTCQ-012
500P3100-101MT (STC #SR09213RC)	Blade Assembly, Tail Rotor	MDHI 369D, E (H3WE)	HTCQ-012
500P3100-103 (STC #SR09213RC)	Blade Assembly, Tail Rotor	MDHI 369D, E (H3WE)	HTCQ-012
500P3100-103T (STC #SR09213RC)	Blade Assembly, Tail Rotor	MDHI 369D, E (H3WE)	HTCQ-012

Approved: _____


Vice President, Quality Assurance

12902 South Broadway • Los Angeles, California 90061

Sheet xviii of xxvii – HTC Proprietary Data Not to be Distributed

HELICOPTER TECHNOLOGY COMPANY – REPAIR STATION #HQPR671X**Introduction Section**Change Letter: **K**Change Date: **04/19/2017****VI. Capabilities List – Cont.**

Part Number	Description	Make/Model	Data Source
500P3100-105 (STC #SR09213RC)	Blade Assembly, Tail Rotor	MDHI 369D, E (H3WE)	HTCQ-012
500P3100-301 (STC #SR01282LA)	Blade Assembly, Tail Rotor	MDHI 369D, E (H3WE)	HTCQ-012
500P3100-301I (STC #SR01282LA)	Blade Assembly, Tail Rotor	MDHI 369D, E (H3WE)	HTCQ-012
500P3100-301IT (STC #SR01282LA)	Blade Assembly, Tail Rotor	MDHI 369D, E (H3WE)	HTCQ-012
500P3100-301M (STC #SR01282LA)	Blade Assembly, Tail Rotor	MDHI 369D, E (H3WE)	HTCQ-012
500P3100-301MT (STC #SR01282LA)	Blade Assembly, Tail Rotor	MDHI 369D, E (H3WE)	HTCQ-012
500P3100-303 (STC #SR01282LA)	Blade Assembly, Tail Rotor	MDHI 369D, E (H3WE)	HTCQ-012
500P3100-303T (STC #SR01282LA)	Blade Assembly, Tail Rotor	MDHI 369D, E (H3WE)	HTCQ-012
500P3100-305 (STC #SR01282LA)	Blade Assembly, Tail Rotor	MDHI 369D, E (H3WE)	HTCQ-012


Approved: 
Vice President, Quality Assurance

12902 South Broadway • Los Angeles, California 90061

Sheet xix of xxvii – HTC Proprietary Data Not to be Distributed

HELICOPTER TECHNOLOGY COMPANY – REPAIR STATION #HQPR671X**Introduction Section**Change Letter: **K**Change Date: **04/19/2017****VI. Capabilities List – Cont.**

<u>Part Number</u>	<u>Description</u>	<u>Make/Model</u>	<u>Data Source</u>
500P3300-501 (STC #SR01282LA)	Blade Assembly, Tail Rotor	MDHI 369A, H, HE, HM, HS (H3WE)	HTCQ-012
500P3300-501I (STC #SR01282LA)	Blade Assembly, Tail Rotor	MDHI 369A, H, HE, HM, HS (H3WE)	HTCQ-012
500P3300-501IT (STC #SR01282LA)	Blade Assembly, Tail Rotor	MDHI 369A, H, HE, HM, HS (H3WE)	HTCQ-012
500P3300-501M (STC #SR01282LA)	Blade Assembly, Tail Rotor	MDHI 369A, H, HE, HM, HS (H3WE)	HTCQ-012
500P3300-501MT (STC #SR01282LA)	Blade Assembly, Tail Rotor	MDHI 369A, H, HE, HM, HS (H3WE)	HTCQ-012
500P3300-503 (STC #SR01282LA)	Blade Assembly, Tail Rotor	MDHI 369A, H, HE, HM, HS (H3WE)	HTCQ-012
500P3300-503T (STC #SR01282LA)	Blade Assembly, Tail Rotor	MDHI 369A, H, HE, HM, HS (H3WE)	HTCQ-012
500P3300-505 (STC #SR01282LA)	Blade Assembly, Tail Rotor	MDHI 369A, H, HE, HM, HS (H3WE)	HTCQ-012
500P3500-701 (STC #SR01282LA)	Blade Assembly, Tail Rotor	MDHI 369FF (H3WE)	HTCQ-012

Approved: 
Vice President, Quality Assurance

12902 South Broadway • Los Angeles, California 90061

Sheet xx of xxvii – HTC Proprietary Data Not to be Distributed

HELICOPTER TECHNOLOGY COMPANY – REPAIR STATION #HQPR671X**Introduction Section****Change Letter: K****Change Date: 04/19/2017****VI. Capabilities List – Cont.**

<u>Part Number</u>	<u>Description</u>	<u>Make/Model</u>	<u>Data Source</u>
500P3500-701I (STC #SR01282LA)	Blade Assembly, Tail Rotor	369FF (H3WE)	HTCQ-012
500P3500-701IT (STC #SR01282LA)	Blade Assembly, Tail Rotor	369FF (H3WE)	HTCQ-012
500P3500-701M (STC #SR01282LA)	Blade Assembly, Tail Rotor	369FF (H3WE)	HTCQ-012
500P3500-701MT (STC #SR01282LA)	Blade Assembly, Tail Rotor	369FF (H3WE)	HTCQ-012
500P3500-703 (STC #SR01282LA)	Blade Assembly, Tail Rotor	369FF (H3WE)	HTCQ-012
500P3500-703T (STC #SR01282LA)	Blade Assembly, Tail Rotor	369FF (H3WE)	HTCQ-012
500P3500-705 (STC #SR01282LA)	Blade Assembly, Tail Rotor	369FF (H3WE)	HTCQ-012
369D21120-501 (TC # H3WE, HTC P/N 500P2100-101)	Blade Assembly, Main Rotor	MDHI 369D, E (H3WE)	HTCQ-004
369D21120-503 (TC # H3WE, HTC P/N 500P2100-103)	Blade Assembly, Main Rotor	MDHI 369D, E (H3WE)	HTCQ-004

Approved: 
Vice President, Quality Assurance

12902 South Broadway • Los Angeles, California 90061

Sheet xxi of xxvii – HTC Proprietary Data Not to be Distributed

HELICOPTER TECHNOLOGY COMPANY – REPAIR STATION #HQPR671X**Introduction Section**Change Letter: **K**Change Date: **04/19/2017****VI. Capabilities List – Cont.**

Part Number	Description	Make/Model	Data Source
369D21120-505 (TC # H3WE, HTC P/N 500P2100-105)	Blade Assembly, Main Rotor	MDHI 369D, E (H3WE)	HTCQ-004
369D21121-501 (TC # H3WE, HTC P/N 500P2300-501)	Blade Assembly, Main Rotor	MDHI 369FF, 500N, 600N (H3WE)	HTCQ-004
369D21121-503 (TC # H3WE, HTC P/N 500P2300-503)	Blade Assembly, Main Rotor	MDHI 369FF, 500N, 600N (H3WE)	HTCQ-004
369D21121-505 (TC # H3WE, HTC P/N 500P2300-505)	Blade Assembly, Main Rotor	MDHI 369FF, 500N, 600N (H3WE)	HTCQ-004
369D21123-501 (TC # H3WE, HTC P/N 500P2100-301)	Blade Assembly, Main Rotor	MDHI 369A, H, HE, HM, HS (H3WE)	HTCQ-004
369D21123-503 (TC # H3WE, HTC P/N 500P2100-303)	Blade Assembly, Main Rotor	MDHI 369A, H, HE, HM, HS (H3WE)	HTCQ-004
369D21123-505 (TC # H3WE, HTC P/N 500P2100-305)	Blade Assembly, Main Rotor	MDHI 369A, H, HE, HM, HS (H3WE)	HTCQ-004

Approved: 
Vice President, Quality Assurance

12902 South Broadway • Los Angeles, California 90061

Sheet xxii of xxvii – HTC Proprietary Data Not to be Distributed

HELICOPTER TECHNOLOGY COMPANY – REPAIR STATION #HQPR671X**Introduction Section**Change Letter: **K**Change Date: **04/19/2017****VI. Capabilities List – Cont.**

<u>Part Number</u>	<u>Description</u>	<u>Make/Model</u>	<u>Data Source</u>
369D21640-501 (TC # H3WE, HTC P/N 500P3100-101)	Blade Assembly, Tail Rotor	MDHI 369D, E (H3WE)	HTCQ-012
369D21640-503 (TC # H3WE, HTC P/N 500P3100-101I/M)	Blade Assembly, Tail Rotor	MDHI 369D, E (H3WE)	HTCQ-012
369D21640-503T (TC # H3WE, HTC P/N 500P3100-101IT/MT)	Blade Assembly, Tail Rotor	MDHI 369D, E (H3WE)	HTCQ-012
369D21640-505 (TC # H3WE, HTC P/N 500P3100-103)	Blade Assembly, Tail Rotor	MDHI 369D, E (H3WE)	HTCQ-012
369D21640-505T (TC # H3WE, HTC P/N 500P3100-103T)	Blade Assembly, Tail Rotor	MDHI 369D, E (H3WE)	HTCQ-012
369D21640-507 (TC # H3WE, HTC P/N 500P3100-105)	Blade Assembly, Tail Rotor	MDHI 369D, E (H3WE)	HTCQ-012
369D21641-501 (TC # H3WE, HTC P/N 500P3100-301)	Blade Assembly, Tail Rotor	MDHI 369D, E (H3WE)	HTCQ-012

Approved: 
Vice President, Quality Assurance

12902 South Broadway • Los Angeles, California 90061

Sheet xxiii of xxvii – HTC Proprietary Data Not to be Distributed

HELICOPTER TECHNOLOGY COMPANY – REPAIR STATION #HQPR671X**Introduction Section**Change Letter: **K**Change Date: **04/19/2017****VI. Capabilities List – Cont.**

Part Number	Description	Make/Model	Data Source
369D21641-503 (TC # H3WE, HTC P/N 500P3100-301I/M)	Blade Assembly, Tail Rotor	MDHI 369D, E (H3WE)	HTCQ-012
369D21641-503T (TC # H3WE, HTC P/N 500P3100-301IT/MT)	Blade Assembly, Tail Rotor	MDHI 369D, E (H3WE)	HTCQ-012
369D21641-505 (TC # H3WE, HTC P/N 500P3100-303)	Blade Assembly, Tail Rotor	MDHI 369D, E (H3WE)	HTCQ-012
369D21641-505T (TC # H3WE, HTC P/N 500P3100-303T)	Blade Assembly, Tail Rotor	MDHI 369D, E (H3WE)	HTCQ-012
369D21641-507 (TC # H3WE, HTC P/N 500P3100-305)	Blade Assembly, Tail Rotor	MDHI 369D, E (H3WE)	HTCQ-012
369D21642-501 (TC # H3WE, HTC P/N 500P3500-701)	Blade Assembly, Tail Rotor	MDHI 369FF (H3WE)	HTCQ-012
369D21642-503 (TC # H3WE, HTC P/N 500P3500-701I/M)	Blade Assembly, Tail Rotor	MDHI 369FF (H3WE)	HTCQ-012


Approved: 
Vice President, Quality Assurance

12902 South Broadway • Los Angeles, California 90061

Sheet xxiv of xxvii – HTC Proprietary Data Not to be Distributed

HELICOPTER TECHNOLOGY COMPANY – REPAIR STATION #HQPR671X**Introduction Section**Change Letter: **K**Change Date: **04/19/2017****VI. Capabilities List – Cont.**

Part Number	Description	Make/Model	Data Source
369D21642-503T (TC # H3WE, HTC P/N 500P3500-701IT/MT)	Blade Assembly, Tail Rotor	MDHI 369FF (H3WE)	HTCQ-012
369D21642-505 (TC # H3WE, HTC P/N 500P3500-703)	Blade Assembly, Tail Rotor	MDHI 369FF (H3WE)	HTCQ-012
369D21642-505T (TC # H3WE, HTC P/N 500P3500-703T)	Blade Assembly, Tail Rotor	MDHI 369FF (H3WE)	HTCQ-012
369D21642-507 (TC # H3WE, HTC P/N 500P3500-705)	Blade Assembly, Tail Rotor	MDHI 369FF (H3WE)	HTCQ-012
369D21643-501 (TC # H3WE, HTC P/N 500P3300-501)	Blade Assembly, Tail Rotor	MDHI 369A, H, HE, HM, HS (H3WE)	HTCQ-012
369D21643-503 (TC # H3WE, HTC P/N 500P3300-501I/M)	Blade Assembly, Tail Rotor	MDHI 369A, H, HE, HM, HS (H3WE)	HTCQ-012
369D21643-503T (TC # H3WE, HTC P/N 500P3300-501IT/MT)	Blade Assembly, Tail Rotor	MDHI 369A, H, HE, HM, HS (H3WE)	HTCQ-012


Approved: 
Vice President, Quality Assurance

12902 South Broadway • Los Angeles, California 90061

Sheet xxv of xxvii – HTC Proprietary Data Not to be Distributed

HELICOPTER TECHNOLOGY COMPANY – REPAIR STATION #HQPR671X**Introduction Section**Change Letter: **K**Change Date: **04/19/2017****VI. Capabilities List – Cont.**

Part Number	Description	Make/Model	Data Source
369D21643-505 (TC # H3WE, HTC P/N 500P3300-503)	Blade Assembly, Tail Rotor	MDHI 369A, H, HE, HM, HS (H3WE)	HTCQ-012
369D21643-505T (TC # H3WE, HTC P/N 500P3300-503T)	Blade Assembly, Tail Rotor	MDHI 369A, H, HE, HM, HS (H3WE)	HTCQ-012
369D21643-507 (TC # H3WE, HTC P/N 500P3300-505)	Blade Assembly, Tail Rotor	MDHI 369A, H, HE, HM, HS (H3WE)	HTCQ-012
369D21100 All Variants	Blade Assembly, Main Rotor	MDHI 369D, E (H3WE)	HTCQ-004
369A1100 All Variants	Blade Assembly, Main Rotor	MDHI 369A, H, HE, HM, HS (H3WE)	HTCQ-004
369D21102 All Variants	Blade Assembly, Main Rotor	MDHI 369FF, 500N, 600N (H3WE)	HTCQ-004
269A6035-021	Blade Assembly, Tail Rotor	SAC 269A, 269A-1, 269B, (4H12)	HTCQ-017
269A6035-023	Blade Assembly, Tail Rotor	SAC 269C, 269C-1, 269D (4H12)	HTCQ-017
369A5518-601	Shaft Assembly, Tail Rotor Drive	MDHI 369A, H, HE, HM, HS (H3WE)	HTCQ-013

Approved: 
Vice President, Quality Assurance


12902 South Broadway • Los Angeles, California 90061

Sheet xxvi of xxvii – HTC Proprietary Data Not to be Distributed

HELICOPTER TECHNOLOGY COMPANY – REPAIR STATION #HQPR671X**Introduction Section**Change Letter: **K**Change Date: **04/19/2017****VI. Capabilities List – Cont.**

<u>Part Number</u>	<u>Description</u>	<u>Make/Model</u>	<u>Data Source</u>
369D25518-501	Shaft Assembly, Tail Rotor Drive	MDHI 369D, E (H3WE)	HTCQ-013
369D25518-503	Shaft Assembly, Tail Rotor Drive	MDHI 369FF (H3WE)	HTCQ-013
500N5200-BSC	Shaft Assembly, Fan Drive	MDHI 500N, 600N (H3WE)	HTCQ-013
269A1185-001	Blade Assembly, Main Rotor	SAC 269C, 269C-1, 269D (4H12)	HTCQ-004
269D1120-001	Blade Assembly, Tail Rotor	SAC 269D (4H12)	HTCQ-004
269D1120-009	Blade Assembly, Tail Rotor	SAC 269D (4H12)	HTCQ-004
204P2100-101	Blade Assembly, Main Rotor	UH-1H, UH-1B, TH-1F, UH-1F, UH-1P, 204B, 205A, and 205A-1 (Various)	HTCQ-014
204-011-250-113	Blade Assembly, Main Rotor	UH-1H, UH-1B, TH-1F, UH-1F, UH-1P, 204B, 205A, and 205A-1 (Various)	HTCQ-014
269A6040-007	Shaft Assembly, Tail Rotor	SAC 269C, 269C-1, 269D (4H12)	HTCQ-013
269A6040-009	Shaft Assembly, Tail Rotor	SAC 269C, 269C-1, 269D (4H12)	HTCQ-013

Approved: _____


Vice President, Quality Assurance

12902 South Broadway • Los Angeles, California 90061

Sheet xxvii of xxvii – HTC Proprietary Data Not to be Distributed